

319 West Madison Street Durand, WI 54736 Phone 15-672-4444 Fax 715-672-5 02 www.WeissC. toice.com

HISTORY OF PROPERTY

The following information supplements the attached Seller's Property Condition Report.

For the property located at	67 MURP	44 Rd B.R.F. W. 54665
Age of Home?	14	
Age of Roof?	14	
Age of Furnace?	14	GROUND WATER HEAT PLAN
Age of Central Air?	14	£ 734.
Age of Water Heater?	af and	PROSE STREET PROCESSES AND
Age of Well?	101	Service - Mind Milk State phonographic and a distinguishment of the Commission of th
Age of Septic System?	11	
Septic Pumped How Often?	3 yrs	diada. Sandal faringa yang aga aga aga paga pandanan ani sada dan dan dan dan dan dan dan dan dan
Is Water Softener Rented?	Yes No	
Any roof repairs by you/previous owner?	Yes No	
Has the electrical system been upgraded?	Yes No	
Has the plumbing system been upgra led?	Yes (No)	
Any leaking, cracked or broken windows?	Yes No	
Do all windows open?	(Yes) No	
Have you ever paid flood insurance on property?	Yes (Va)	PROSE- IMPONENTIAN AND AND AND AND AND AND AND AND AND A
Has property ever been damaged by fire?	Yes (No)	SORTIAL TOTAL PROSPERSION CONTINUES TO THE CONTINUES TO T
is anything on the property not connected to septic that should be?	Yes No	
Has sewer line ever been cleaned out or broken?	Yes No	
Have you ever had bats or treated for bats?	Yes No	
Has instilation been added?	Yes No	
Are there keys for all doors?	(Yes) No	
Are there heat vents in every room?	(Yes) No	
Any water in basement?		ONE TIME
Dampness Ba	ackup thr 1 floor drain	
Improper landscapingO	ther – Please specify:	N/A NO

Any problems with built-in appli	iance3?		
Stove Range Ho	ood Disposa	Mic owave	Dishwashe
Other - Please specify:	NO		
Do you know who the builder wa	as?NoX Yes	Name: ZONNAL	EL BANTIEVE
Curren: Homeowner's Insurance	CO. ERIE I	NS	8
Utility Companies: Gas Office	ra	Electric TACK	COO FLORTA
Phone CENTURY	LIVE Cable	0)154	and are an analysis of the second constraints of the second constraints and the second constraints of the second constrain
Water/Sewer MA	011	A. H.B.	
Average Monthly Utility Costs:			
	ol. st		
Gas \$ <u>GO</u> Natur	al: > Fropai	ne: \$ Oi	S Department of the control of the c
Electric: \$ 200 Ca		Pro	mine andre
f you are not using cable, is it ava	ailable to this house	X Ve DISH	
Do you have access to high-speed			
low is refuse or trash handled?			
lefuse/ rash per year 3_40	Provider & pickup day?	NIA	menter in general and the following of the following medical and conduct angular device in the contract of the
re you equired to recycle?	X ∖es No	and interpretation and facilities and facilities are for the facilities and the second and the s	ert de Amaark megretike i reditional format indige dieser, danse treditional betrekken (vor til Edward).
yes, how is the recycling handle		1 P 6 E	
done during your ownership, or	if otherwise known what	Was used as a reference	Fahrer than an an ada a 12
then ferice, shed or garage was e	rected?	. Has asee as a reference	e for property in les
Location Report Sui		enacify.	
with grave all to be	and the second s	JACUIY.	Security of Aspendies (Security), lighter care
lease note any other information	that a new homeou nor w	unuld find control to be	a who was a late
roperty or the neighborhood:	A STATE OF THE PARTY OF THE PAR	oddd mie dseidi te kilo	w about this
10 2009	FR & TWAKEY	11. 5.31-1	
OKHA DE	FIX 4 1 WOREY	HULLIU O	
e information contained in this re	enor is true and correct t	o the hear of my	1
ℓ . 1 ℓ .			
ned: St. A. St.	Date Signed:		
Seller	Date Ji ned:	Soller	and any angular the subserve of the makes and any through any
*	published deliver re se tt	₩ ⁺ 18₩\$	Date
th my signature I acknowledge re	eceip of a copy of this ren	port.	
111			
ned: X6/X	Sie rod-	- No. of an Estimate processor and polycyte Makelakov.	
Seller	Date Dig reci.	Se ller	Data

Write-up on History of House at W10367 Murphy Road

- A. House was a stick-built house, finished in **2002** and built by **Connely Constructon** of Holmen, Wi.
- B. House is heavily insulated & top-end executive level through-out.
- C. House include 3-season porch with Hot tub.
- D. Also includes extra-large Trex deck area & pool.
- E. House has 18' vaulted, cedar ceilings.
- F. Master bath has both **shower enclosure** with extra sprays & **heart** shaped tub with jets.
- G. Heated garage with both inside & outside dog kennels & runs.

Improvements:

- A. Trex deck topping \$21K
- B. 2015 Quartz countertops \$10K

Out-tuildings:

- A. 32x40 Machine shed/2nd garage with concrete floors lighting & power.
- B. Horse barn with ½ concrete floors & other half set for two stalls.

 Barn is lighted & has power.
- C. White fence pasture area.
- D. Area for garden and/or orchard.

History of Hunting Land at W10367 Murphy Road

- A. **Purchased in 1992** this property includes **241.75** acres or wooded pak ridges, poplar & pine stands.
- B. Also includes approx. 10 acres of tillable & extensive trails system.
- C. **1993-2016** developed trails system, 9 fc od plots, installed ladder stands & built box blinds.
- D. 2004 started QDM practices vi/14-16' and 8 pt. rr inimums on bucks and began Fall & after-season trail cam population surveys.
- E. 2005 Went into closed MFL and instituted practice of only allowing 2 hunters to hunt this property
- F. 2006 Did select cuts and strategic sanct Jary clear cuts to improve quality of food & cover.
- G. 2007 Built 4 wildlife ponds to assure water was always available and started mineral licks.
- H. 2008 Began leaving 5-6 acres of standing corn over the winter to help deer & turkeys go into Spring in good shape.
- 1. 2009 Increase buck harvest minimums to 16-18' spreads and 8 points or better with tall tines.
- J. 2010 Buck to Doe ratio reached 1/1 and we began to shoot 1 doe for every buck harvested.
- K. 2011 Reduced hunters on the property to just (1) me.

Current Situation (last 5 years)

- 1. Have taken a 140-1262 class buck each year.
- 2. Buck/doe ratio is 1/1 with approx. 12-15 bucks on property by 5 successive after season trail cam surveys.
- 3. Approx. 80-100 turkeys here during the winter.